

**From:** [Mescher, Jean](#)  
**To:** [Kilburn, Dianna](#); [Egan, Marilyn](#)  
**Cc:** [Shawn Ghose/R6/USEPA/US@EPA](#)  
**Subject:** FW: [FWD: Monthly Arkwood Results (4/19/11)], et al.  
**Date:** 05/02/2011 02:28 PM  
**Attachments:** [1104241.pdf](#)

---

Dianna and Marilyn,

Please see attached results: 12.5 ppb PCP at the spring mouth and <5.00 ppb PCP at the weir. Per Jim's note below, the injection well was turned off on April 19. Once the spring flow decreases to about 25 gpm or less, we should be able to start looking for possible rebound effects.

Jean

---

**From:** [jfleur@oxfordeands.com](mailto:jfleur@oxfordeands.com) [mailto:[jfleur@oxfordeands.com](mailto:jfleur@oxfordeands.com)]  
**Sent:** Monday, May 02, 2011 10:32 AM  
**To:** Mescher, Jean  
**Subject:** [FWD: Monthly Arkwood Results (4/19/11)], et al.

Jean,

Good morning. Attached are the April sampling results for the Arkwood site. The last couple weeks have been very interesting. On April 19, the injection well was shut off. In the next two weeks, the site has seen approximately 13 inches of rain.

If you have any questions or would like to discuss site operations, please call me.

Best Regards,

*Jim*

James E. Fleer  
Principal Engineer  
Oxford Environmental and Safety, Inc.  
913-706-3422  
[jfleur@oxfordeands.com](mailto:jfleur@oxfordeands.com)

----- Original Message -----

Subject: Monthly Arkwood Results (4/19/11)  
From: "Sydney James" <[sjames@arkansasanalytical.com](mailto:sjames@arkansasanalytical.com)>  
Date: Wed, April 27, 2011 4:52 pm  
To: <[jfleur@oxfordeands.com](mailto:jfleur@oxfordeands.com)>

Thanks,  
Sydney James Randles

11701 Interstate 30  
Bldg. 1, Ste. 115  
Little Rock, AR 72209  
501-455-3233  
501-455-6118 (fax)

This e-mail and any attachments are confidential. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information and you should destroy the e-mail and any attachments or copies.